

23334

ILS RWY 33 (SA CAT I & II)
BANGOR INTL (BGR)

SA CAT I: Requires specific OPSPEC, MSPEC, or LOA approval and use of HUD to DH.
SA CAT II: Reduced lighting: requires specific OPSPEC, MSPEC, or LOA approval and use of Autoland or HUD to touchdown.

MISSED APPROACH: Climb to 3000 on heading 330° and on BGR VORTAC R-333 to IKEXE/BGR VORTAC 11.9 DME/RADAR and hold.

ALTERNATE MISSED APCH FIX

039°

219°

17.9 MLT

R-219

Chan 126

HOSEP

MLT 37.2



3000 ↑	hdg 330°	BGR R-333	IKEXE BGR <u>11.9</u> RADAR	One Minute Holding Pattern	
CATEGORY	A	B	C	D	
S-ILS 33	SA CAT I RA 173/14		150 DA 313		
S-ILS 33	SA CAT II RA 103/12		100 DA 263		

TDZ/CL Rwy 15
HIRL Rwy 15-33

BANGOR, MAINE
Amdt 13 27APR17

44°48'N-68°50'W

BANGOR INTL (BGR)
ILS RWY 33 (SA CAT I & II)