

LOC/DME I-SMF <u>111.1</u> Chan 48	APP CRS 168°	Rwy Idg 8598 TDZE 25 Apt Elev 27
--	------------------------	---

ILS RWY 17R (CAT II & III)
SACRAMENTO INTL (SMF)

Aircraft not GPS equipped - RADAR required for procedure entry.
DME or RADAR required. RNP APCH-GPS. From TENCO.


ALSF-2



MISSED APPROACH: Climb to 500 then climbing right turn to 2000 on heading 350° and SAC VORTAC R-329 to GRIME INT/SAC 35.2 DME and hold.


Simultaneous approach authorized.

D-ATIS	NORCAL APP CON				CAPITOL TOWER		GND CON		CLNC DEL		CPDLC
126.75	125.4	259.1 (W-NE)	125.25 (E-SE)	257.9 (SW)	125.7	256.7	121.7	256.7	121.1	256.7	



ALTERNATE MISSED APCH FIX

WILLIAMS
ILA $\ddot{::}\ddot{::}$
114.4
Chan 91

[illegible]

CATEGORY II & III ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED