

TACAN DWG
Chan 2

APCH CRS
183°

Rwy Idg
8025
TDZE
191
Arpt Elev
195

AL-699 [USAF]

DUKE FLD (EGLIN AF AUX NR3) (KEGI)

* When ALS inop, increase RVR to 55, vis to 1 mile.

ALSF-1

MISSED APPROACH: Climb on DWG R-003 to 9 DME (BUBBE), then climbing left turn to 2300 direct DWG R-033/23 DME (PAPPY) and hold.

ATIS ★
244.575

EGLIN APP CON
125.1 281.45 (271°- 089°)
132.1 360.6 (090°- 270°)

TOWER ★
133.2 290.425

GND CON
123.25 251.125

PROCEDURE EFFECTIVE BY NOTAM

Missed Approach requires use of RNAV or ATC RADAR monitoring.

WARRINGTON
Chan 2 DWG

EMERG SAFE ALT 100 NM 3500

VGSI and descent angles not coincident (Angle 3.00/TCH 60).

CATEGORY	C	D	E
S-18*	560/35	369 (400-5%)	
CIRCLING	700-1½ 505 (600-1½)	760-2 565 (600-2)	780-2 585 (600-2)

ELEV 195

TDZE 191

VALPARAISO, FLORIDA

30°39'N-86°31'W

DUKE FLD (EGLIN AF AUX NR3) (KEGI)

Orig 23MAR23

HI-TACAN Y RWY 18