

GLENDALE, ARIZONA

HI-TACAN RWY 3R

TACAN LUF
Chan 77

APCH CRS
029°

Rwy Idg 9912
TDZE 1074
Arpt Elev 1084

AL-321 [USAF]

LUKE AFB (KLUF)

ALSF-1

A1

MISSED APPROACH: Climbing to 4000, intercept LUF TACAN R-033 to 12 DME (JOKVI). Contact Luke APP CON.

ATIS ★
134.925 269.9

APP CON
118.15 363.125

TOWER ★
119.1 379.9

GND CON
133.175 335.8

CLNC DEL
126.25 273.475

Map details: R-318, HOLD FL220, LUF 30, 2615 (IAF) LENNI LUF 22, CASIB LUF 16, OSELE LUF 16, R-285, LUF 16, Arc, 4252, 1239, LUKE Chan 77 LUF, JUPVA LUF 6, 029°, 1768, (IF) WUNBA LUF 16, R-209, 4533, R-033, 1654, JOKVI LUF 12, 5909, 4203, 4565, 5000, 3000, 248, 068, (c), (b), (a).

EMERG SAFE ALT 100 NM 17,000

MSA LUF 2.5 NM 5800

LENNI 22
12,000
138°

CASIB 16
7000

OSELE R-285 16
5000

WUNBA 16
2800

JUPVA 6
22

CAVAN 1.4

TACAN

4000 LUF R-033 12

JOKVI 12

ELEV 1084

TDZE 1074

CATEGORY C D E

S-3R ★ 1560/50 486 (500-1)

CIRCLING NOT AUTHORIZED

1296
1179

TWR 1242

029° 5.2NM from FAF

HIRL all rws

21R

21L

3R

3L

10,000 x 150

29912 x 150

A1

P

P

P

P

★