(STPHN3.STPHN) 23166 STPHN THREE DEPARTURE (RNAV) UNIVERSITY OF OKLAHOMA WESTHEIMER (OUN) NORMAN, OKLAHOMA



DEPARTURE ROUTE DESCRIPTION

TAKEOFF RUNWAY 3:Climb on heading 032° to 1700, then left turn heading 356°or as assigned by ATC, expect RADAR vectors to SQRRL, thenceTAKEOFF RUNWAY 18:Climb on heading 176° to 1700, then heading 176°or as assigned by ATC, expect RADAR vectors to SQRRL, thenceTAKEOFF RUNWAY 21:Climb on heading 212° to 1700, then left turn heading 176°or as assigned by ATC, expect RADAR vectors to SQRRL, thenceTAKEOFF RUNWAY 21:Climb on heading 356° to 1700, then left turn heading 176°or as assigned by ATC, expect RADAR vectors to SQRRL, thenceTAKEOFF RUNWAY 36:Climb on heading 356° to 1700, then heading 356°or as assigned by ATC, expect RADAR vectors to SQRRL, thence

.... on track 272° to STPHN, then on (transition). Maintain 3000 or as assigned by ATC. Expect filed altitude 10 minutes after departure.

BFFFY TRANSITION (STPHN3.BFFFY) ZEEWE TRANSITION (STPHN3.ZEEWE)

STPHN THREE DEPARTURE (RNAV) (STPHN3.STPHN) 07DEC17

V